

[Guide] - Bevi Alert Center - Inlet Water Unavailable



Overview

You have been directed to this page because you have encountered a Machine Alert - "Inlet Water Unavailable" This document will outline how to work with the Bevi V2 unit to diagnose and fix this issue.

 partners.bevi.co support@bevi.co 866-704-2384 	2	DVP Machine ID:	2 01 . DVP-01		НОМЕ	OPEN DOOR
QUICK READINGS		Machine Alerts				
Internal water pressure	71 psi 864 psi	ALERT	MACHINE STATE	REPORTED	STATUS	
CO2 temp	31°C	Inlet Water Unavailable	Out of Order	9/27/21	Open	
Chiller temp	0.7°C					
Heater temp	91°C					
TROUBLESHOOTING	TOOLS					
		Warning: Only trained Bevi technicians s untrained individuals may result in dama	should be resolving the Ma age to the Bevi machine. C	chine Alerts a ontact your B	bove. Troublesho evi provider for c	oting performed by ssistance.



Frequently Asked Questions

Q: What caused this alert - various symptoms that may have caused alert to fire

A: Customer dispensed and only flavor came out

A: Dispense was halted because the machine detected no additional water flowing into the machine

Q. What do the different alert status mean

- A. <u>Not Started</u>- The machine has detected the alert, but no service has been initiated to fix the issue.
- B. <u>Open</u> Someone has tried to fix the issue, but it is still unresolved.
- C. <u>Resolved</u> A technician has serviced the machine and the machine was working fine as of the date reported "Resolved"

Q. What do the Buttons on the Machine Alerts page mean?

- A. <u>Troubleshoot</u> Selecting this button will take you to a troubleshooting document for this issue
- B. <u>Troubleshooting Tools -</u> These are a set of readings and controls to help you diagnose and test results.

Questions Answered in this Document

Q: How to troubleshoot the "No Inlet Water Available" Alert to diagnose the exact issue and resolve

Q. What solutions are available to fix this issue

Required Tools & Materials

• Number 2 Screwdriver



Task 1: Open the Troubleshooting Tools to be able to understand what is happening.

1. Select the "Troubleshooting Tools" button to open up the screen below





Task 2: Look in the "Water Section" of the Data area of the troubleshooting tools

SOFTware Appended Appended Andreid OS	partners.bevi.co support@bevi.co 🛜 866-704-2384	DVP Mechine ID	2 01 DVP-01	BACK TO ALERTS	OPEN DOOR
Application Habbin Watchidog 3.0.0 Android 05 Android 0 Bystem Lit Hidden Hidden Electrical Flavors And Enhancements Modes Connection BevlaxscelleWIFI Celular Celular Connection BevlaxscelleWIFI Celular Modes Connection BevlaxscelleWIFI Connection BevlaxscelleWIFI Connection BevlaxscelleWIFI Connection BevlaxscelleWIFI Codid weter POUR Hot water POUR Bparkling water POUR Pour POUR	SOFTWARE	Controls		Data	
Android OS Android OS Android OS Android OS Bytem Li Hidden Hitternet Electrical Flavors And Enhancements Max. ice detected Modes Competition Bit. Do Bit. Do MB Mes. ice detected DisPEnse POUR Coid water POUR Bparkling water POUR Pour <td>App 14.0 UPDATE</td> <td>Chiller</td> <td></td> <td>Chiller</td> <td>~</td>	App 14.0 UPDATE	Chiller		Chiller	~
Pyratem Li Hidden Pyratem Li Hidden INTERNET Flavors And Enhancements Corruection Bev(axcelle_WiFi Corruection Bev(axcelle_WiFi Connection Connection Barkling water POUR Pour Pour Barkling water POUR Pour Pour Bare leak detected yes Filter Installed 10/01/2021 Internal water pressure 60 pul	Android OS Android 9	Water		Full	yes
INTERNET Connection Bevlaxcelle_WIF Connection Bevlaxcelle Modes Cellular Cellular disabled BM D MEl Number Cold water POUR Hot water POUR Barkling water POUR Barkling water POUR Hot water POUR Hit water POUR	System Ul Hidden	Electrical		Min. Ice detected	yes
INTERNET Connection Bev/axcelle_WiFi Modes Chiller temp 0.700 Cellular Cellular disabled Modes Coll temp 2870 SiM ID Coll temp 2870 Coll temp 2870 SiM ID Coll temp Coll temp 2870 Coll temp 2870 Dispension Fen ourrent 0.04 amps Heater temp 9100 Base leak detected yes Base leak detected yes Filter installed 10/01/2025 Intemal water pressure 60 pal		Elavors And Enhancements		Max. ice detected	yes
Connection Bev/Lexcelle_WiFI Modes Cabonator full yes Cellular Cellular disabled C02 temp 28°C SIM ID Co2 pressure 807 psi IMEI Number Compressor current 0.03 amps DispEnse Cod water POUR Hot water POUR Heater current 0.04 amps Hot water POUR Heater current 0.10 amps Heater current 0.10 amps Heater temp 0°C Base leak detected yes Filter installed 10/01/20281 Internal water pressure 60 psi Filter installed 10/01/20281	INTERNET	Flavors And Enhancements		Chiller temp	0.7°C
Cellular Cellular disabled C02 temp 28°C SIM ID C02 pressure 807 psl IMEI Number Coopressor current 0.03 amps DISPENSE Coid water POUR Hot water POUR Heater current 0.04 amps Bparkling water POUR Heater current 0.01 amps Hiter installed 10/01/2021 Internal water pressure 60 psl	Connection Bevi,excelle WIFI	Modes		Carbonator full	yes
SM ID C02 pressure 807 psl IMEI Number Compressor current 0.03 amps Fan ourrent 0.04 amps Fan ourrent 0.04 amps Hot water POUR Bparkling water POUR Hot water POUR	Cellular Cellular disabled			CO2 temp	28°C
IMEI Number Compressor current 0.03 amps DISPENSE Fan ourrent 0.04 amps Cold water POUR Heater current 0.01 amps Hot water POUR Heater current 0.01 amps Bparkling water POUR Heater current 0.01 amps Hiter installed 10/01/2021 Internal water pressure 60 pal	SIM ID			CO2 pressure	867 psl
DISPENSE Cold water POUR Water Water Moder Moder	IMEI Number			Compressor current	0.03 amps
Dispense Water Cold water POUR Hot water POUR Sparkling water POUR Filter installed 10/01/2021 Internal water pressure 60 pal				Fan ourrent	0.04 amps
Cold water POUR Hot water POUR Sparkling water POUR Hot water POUR Heater current 0.10 amps Heater temp 01°C Base leak detected yes Filter installed 10/01/2021 Internal water pressure 68 pal	DISPENSE			Water	~
Hot water POUR Sparkling water POUR POUR Heater temp 00°C Base leak detected yes Filter installed 10/01/2021 Internal water pressure 00 pail	Cold water POUR			Heater current	0.10 amps
Bparking water POUR Base leak detected yes Filter installed 10/01/2021 Internal water pressure 00 pail	Hot water POUR			Heater temp	91°C
Filter Installed 10/01/2021 Internal water pressure 00 pair	Sparkling water POUR			Base leak detected	yes
Internal water pressure 66 pai				Filter installed	10/01/2021
				Internal water pressure	00 pai

1. Check internal water pressure by looking in the water section of the troubleshooting tools to see if it is above 0 or less than 0

Task 3 - Reading is 0 or below

- 1. Determine the nature of the alert Check the water source
 - a. Check to see if someone turned off the source water at the valve. This could have happened because someone had to work on other equipment that is attached to the same water source. If the water was shut off, please turn it on.
 - b. Once water supply is on, go to "Controls" section of the Troubleshooting tools, then "Inlet Solenoid" and select "open".



Controls		
Chiller		
Water		^
Heater	OFF	ON
Inlet Solenoid	CLOSE	OPEN
Demand Pump	OFF	ON
Leak Down Test	STA	RT
Electrical		
Flavors And Enhancements		
Modes		

- c. Once completed check to see if internal water pressure has returned to "normal" (Greater than 40 psi)
- d. If not proceed to Task 4

Task 4: Determining the source of the Problem - Check the Bevi water valve between the water source and the Bevi machine

1. Tracing the water line from the back of the Bevi to the source valve, check for any additional shut off valves.



- 2. Check to see if all water valves are in the "On" position On is indicated by the valve knob being "in-line" with the water line.
- 3. If any ball valves are closed, move the valves to the open position (in-line with the water line)
- 4. Check to see if the filter is connected. Disconnect by turning the filter clockwise to disconnect the filter, reseat by turning counterclockwise.



- 5. Go to Controls, Water, then "Inlet solenoid" and select "open"
- 6. Check to see if internal water pressure has returned to normal building pressure If so, the problem has been resolved.
- 7. If the source valves are on, the Bevi valve is on, and a filter is properly installed proceed to Task 5

Task 5: Determining the source of the Problem - Check Manifold 1

Manifold 1 is behind the water line inlet. To access please remove the middle back panel of the Bevi.



Check to see if water is flowing through Manifold 1

a. Go to the front of the machine and remove the ³/₈" tube from the elbow connector the is one the left hand side of the filter head. Remove the Red Clip first, then remove the tube.





- b. Pull the %" line through to the back of the machine and put the line into a bucket.
- c. Using the Controls section, open the inlet solenoid to see if water goes into the bucket.
- d. If water goes into the bucket, the Inlet Solenoid in Manifold 1 is good
- e. If there is no water coming out, and you hear a click, check your source water to see if in fact water is flowing to the Bevi.
- f. If there is no click and no water coming out of the tube, then check power to manifold 1 (Task 6)
- g. Replace the filter supply line back into the filter head making sure to fully insert the tube into the proper marked depth.

NOTE: To avoid leaks, do not forget to add/replace the red tubing clip!



Task 6 - Checking Power to Manifold 1

- 1. Turn off the supply water coming to the Bevi
- 2. Disconnect the water supply line coming into the Bevi
- 3. Unscrew the inlet water plate in front of Manifold 1 (4 screws)





- 4. Remove manifold 1 bracket to access inlet solenoid wiring
 - a. Follow steps 1-7 of Manifold 1 Remove and Replacement Guide
 [Guide]Bevi Standup 2.0 Removal and Replacement Guide Manifo...
- 5. Do a visual inspection to see if the 2 spade-connector plugs to the inlet solenoid on Manifold 1 (the outermost solenoid) are plugged in
 - a. If one or both spade connectors are not plugged in, reseat and check
 - b. If plugged in, visually inspect the entire length of cable to see if it has been cut or broken
 - c. Go to the Controls section of the Troubleshooting Tools and Open/Close the inlet solenoid. If you hear a "Click" the issue is resolved, If no click is heard, continue



d. With a multimeter, check that voltage is coming into the Inlet Solenoid of Manifold 1 by taking off the two spade connectors (Orange/Grey) from the Inlet Solenoid and checking for 24V between two cable-side connectors when turning the Inlet Solenoid "On"





- e. If there is 24 V Replace Manifold 1
 - i. If there is not 24V
 - 1. Remove the upper back panel of the Bevi.
 - 2. Check the BUCB board to see if there is 24V going to Manifold 1.

Warning - Use caution when working with PC boards as you can naturally carry a static charge which could damage the board permanently. If available a static strap should be used. If not available, use caution by only touching the edges of the board and/or the plastic plugs themselves. If using a multimeter, keep your hands on the probes and only place the probe tips where you need to measure to avoid shorts.





6. If after pressing the "On" toggle for the inlet solenoid and looking at your multimeter. If you do not get 24V replace the BUCB



7. If you DO get 24V then replace the cable

Make sure to log your service to clear the Alert

It is important to resolve the machine alert in order to clear the Alert and return the machine to normal operation. After you have performed the service required, navigate to the original alert and select "Mark Resolved". From there, resolve the alert by following the instructions and marking the service with the appropriate action. (see screens below) Marking it correctly will help us eliminate this issue in the future, so please be accurate with your description.

If you are unable to resolve the issue, leave the alert open, otherwise if you resolve the issue WITHOUT fixing it, the alert will return and disable the machine.



C pertuen berico C supportijient ca C 886-784-2386	DVP-13 www.com area look	© salars holds □ regringen ■ DVP-13 mean ↓ MA-104-251 Means
CRUE RELATIVE Mender andre presson - 10 per 100 per 10	Matchine Alerts None None Image: State Sta	CONSISTENT Image: Constraint of Constraints Image: Constraints
C generation of a second secon		