



TECHNICAL BULLETIN - WATERBLOCK FITTING REPLACEMENT

Title	WATERBLOCK FITTING REPLACEMENT
Date	2020-09-24
Author	OLIVIA SCHNEIDER
For Questions Contact	SUPPORT@BEVI.CO 1-866-704-2384
Description	
<p>Bevi is transitioning from the use of a plastic fitting to a metal fitting on the waterblock. This will decrease the likelihood of a leak in the field.</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p>Old Waterblock with Plastic Fitting</p> </div> <div style="text-align: center;">  <p>New Waterblock with Metal Fitting</p> </div> </div>	
FAQs	
<ul style="list-style-type: none"> - Why does the plastic fitting need to be replaced? <ul style="list-style-type: none"> - The plastic fittings currently installed on the waterblock have shown to be the cause of leaks in the field. - How long after installation does the fitting typically fail? <ul style="list-style-type: none"> - There is no indication which fittings fail and when. - Is there a chance that the metal fittings will have the same issue? <ul style="list-style-type: none"> - Bevi tested the metal fittings and was not able to invoke any failures when installed in accordance with the procedure below. - Which Standup units need this fitting replacement? <ul style="list-style-type: none"> - Only the V1.0 and V.75 Units need to have the fitting replaced on the waterblock. V1.5 units do not have waterblocks. 	

Required Tools and Materials

- Water Block - Metal Fitting - Elbow In: 107645-01
(if performing full water block assembly replacement)




- Brass Garden Hose Adapter, $\frac{3}{8}$ " Tube x $\frac{3}{4}$ " FGH: 350-0113
(if performing only fitting replacement)



Remediation Process

Initial Inspection of Fitting

- Inspect the brass fitting for the face seal, O-ring, and collet.



Countertop

- Turn off water to the system.
- Dispense water from the head unit to relieve pressure
- Locate the water block near the filter in the cabinet.



- Remove the (2) red locking clips on either side of the waterblock and detach the tubing from the fittings.



- Remove the waterblock from the system and remove the plastic fitting.



- Check the threads on the waterblock. If any are broken, replace the entire waterblock.



- Inspect the tubing on either side of the waterblock fittings. If worn, either replace or cut the current tube to a fresh portion of the tube.

NOTE: Do not cut tube at an angle



- After the tubing has been inspected, mark the tube used for the fitting $\frac{7}{8}$ " (.875") from the cut end. This step will ensure full insertion of the tubing into the fitting when the water block is reinstalled.



- Set the gallon setting on the waterblock to 3.
NOTE: The 3 and 8 look very similar in the small script on the waterblock, so double check that the arrow is pointing towards the 3.



- Tighten metal fitting until hand tight and mark the waterblock and fitting to indicate this position. Then tighten $\frac{1}{4}$ to $\frac{1}{2}$ turn past the first resistance. The measured gap between fitting and waterblock should be between 0.18" and 0.20".



- Reinstall the waterblock with the new fitting in the cabinet and reconnect the (2) red locking clips.
- The arrow on the waterblock points in the direction of waterflow, which should be into the filter.



NOTE: After reinserting the waterblock, the tube markings created earlier should be visible at the edge of the fitting



- Turn on the water and observe the waterblock. Check for drips over the course of 5 minutes. If any drips are present, tighten the fitting an additional $\frac{1}{4}$ turn. If drips are still present, call tech support.

Standup

- Turn off water to the system.
- Dispense water from the Bevi to relieve pressure
- Locate the water block near the filter in the unit.



- Follow the same procedure detailed above for replacement of the waterblock

- Final installation of the waterblock in the standup unit with the metal fitting

